Wash Care Guidelines for Survive-ARC® garments using 88% Cotton, 12% Nylon and 100% Cotton Fabrics:

Wash care instructions on the label attached to the garment must be adhered to first, in addition to the complementary information below.

- Ø Clean garment thoroughly.
- Ø Detergent only.
- Ø Dry cleanable.
- Ø Turn garment inside out before washing.
- Ø Wash up to 60°C (140°F) for Woven and 40°C (104°F) for Knitted or Fleece fabrics.
- Ø No chlorine bleach or hydrogen peroxide either separately or in detergents.
- Ø No softeners or starch.
- Ø Garments should be washed with like colours.
- Ø Recommended to be washed with garments that are similarly soiled.
- Ø Garment can be tumble dried or line dried.
- Ø Failure to launder properly could adversely affect the flame resistance of the fabric.

Substation-Safety.com
A Division of Powerpoint Engineering Ltd
Unit B6, National Enterprise Park,
Portlaoise, Laois, R32 HH36, Ireland
T: +353 57 866 2162
E: sales@substation-safety.com

Website:
www.substation-safety.com