Additional Garment After care ;

- Garments to stored away from direct sunlight and at room temperature.
- It is recommended garments are stored in dry conditions.
- It is recommended that garments are stored away from direct contact with chemicals, bleaching agents or flammable liquids.

Additional Wearers information ;

- The minimum ATPV value on the risk assessment must be worn across all areas of the wearers body.
- It is recommended cotton under garments are worn under the Survive Arc range as cotton garments are less flammable than synthetics.
- All damaged garments must be replaced as this increases the risk of thermal injuries.
- In the event of an Arc Flash incident the garments must then be deemed not fit for purpose.

Substation-Safety.com
A Division of Powerpoint Engineering Ltd
Unit B6, National Enterprise Park,
Portlaoise, Laois, R32 HH36, Ireland
T: +353 57 866 2162
E: sales@substation-safety.com