



**Mod. SG-117**

**Pneumatic gauge tester**

Before using dielectric gloves for live working, the EN 60903 and IEC 60903 standards recommend a visual inspection by inflating the gloves with air to detect any possible leakages.

The pneumatic tester is a pump system to optimise inflation and visual inspection, especially at the cuff level.  
Class O and OO only.

| Code   | Ref.   |
|--------|--------|
| 545120 | SG-117 |